Fire Prevention Bureau 2601 West Broward Boulevard, 3061 Fort Lauderdale, Florida 33312 (954) 831-8210 www.sheriff.org



Broward Sheriff's Office Department of Fire Rescue and Emergency Services www.sheriff.org

Date:

June 17, 2021

To:

Christy Dominguez, Principal Planner

From:

Lori Hastings, Assistant District Chief / Prevention

Subject:

Nightclub License Renewals

Fire Prevention staff conducted annual fire and life safety inspections of the following nightclubs:

1. CHAPULTEPEC MEXICAN BAR & RESTAURANT (FRIDAYS & SATURDAYS) 23 N.W. 2ND AVENUE 4:00 A.M. CLOSING

2. 831 FEDERAL HIGHWAY ACQUISITION LLC THE BIG EASY CASINO

6:00 A.M. CLOSING

3. CLUB FATE 601 SILKS RUN, UNIT 2499

6:00 A.M. CLOSING

4. FLANIGAN'S SEAFOOD BAR & GRILL
4. N. FEDERAL HIGHWAY

831 N. FEDERAL HIGHWAY

6:00 A.M. CLOSING

5. ORCHID CONCESSIONS, INC. (GULFSTREAM PARK FOOD & BEVERAGE) 901 S. FEDERAL HIGHWAY

6:00 A.M. CLOSING

The inspections were satisfactory with no significant fire hazards or threats to life safety. The fire department staff has no objection to granting the requested conditional use to operate these 6:00 a.m. closing nightclubs.

The remaining nightclubs have outstanding fire and life safety code violations.

6. OCEAN'S 11 LOUNGE SOUTH 800 N. FEDERAL HIGHWAY

6:00 A.M. CLOSING

7. TATIANA RESTAURANT AND NIGHTCLUB 1710 E. HALLANDALE BEACH BLVD.

6:00 A.M. CLOSING

8 THE CHEETAH 100 ANSIN BLVD.

6:00 A.M. CLOSING

If you have any questions please contact me at 954-593-9138.

Cc: Bradley Masters, District Chief

Richard Brown, FPO Hallandale Beach Eric Busenbarrick, Assistant Chief

Thursday, 17 June, 2021

Attn: Marcelo Toledo Gulfstream Park Racing and Casino 901 S Federal Hwy Main Building Hallandale Beach, FL 33009-7124

Re: Initial - Annual Fire Inspection on June 16 2021



Property Address:
Gulfstream Park Racing and Casino
901 S Federal Hwy Main Building
Hallandale Beach, FL 33009-7124

An annual fire inspection of your occupancy revealed no violations at the time of this inspection. Thank you for your commitment to maintaining a fire safe occupancy.

Prior to daily opening you should disinfect the business using the CDC guidelines found

online at bit.ly/2KXkcR5

Peter_Berger@sheriff.org

Inspection Note	es:	
F 0 1 0 -		

For Orchard Concessions for their annual license inspection for renewal purposes for the City of Hallandale Beach.

All hoods and suppression systems were update last week. No violations present in the concession areas.

Inspector:

Property Representative:

Fire Inspector Peter Berger

Marcelo Toledo

Gulfstream Park Racing and Casino Annual Fire Inspection

Inspection on June 16 2021 Violations repaired / total: 0 / 0

Violation/Information Page(s)

General Inspection Information

This inspection was performed using the following chapter of the Florida Fire Prevention Code.

OTHER - Other Code

Tuesday, 8 June, 2021

954-405-5768

Attn: Grace Manager Tatianas Restaurant 1710 E Hallandale Beach Blvd1710 Hallandale Beach, FL 33009



Property Address: Tatianas Restaurant 1710 E Hallandale Beach Blvd Hallandale Beach, FL 33009

Re: Initial - Annual Fire Inspection on June 08 2021

An annual fire inspection of your occupancy revealed the violation(s) listed below. Prompt action to correct the following violation(s) is required. The violation(s) must be corrected within the time frame provided.

Per the Florida Fire Prevention Code (7th Edition), NFPA 1:10.2.1 The owner, operator, or occupant shall be responsible for compliance with this Code.

Inspector:	Property Representative:	
Fire Safety Inspector Jack-Luis Charles, Jr	Grace Manager	
Jack-luis_Charles@sheriff.org		

Tatianas Restaurant Annual Fire Inspection

Inspection on June 08 2021 Violations repaired / total: 0 / 16

Violation/Information Page(s)

General Inspection Information

This inspection was performed using the following chapter of the Florida Fire Prevention Code.

CH13 - Existing Assembly (Ch. 13)

Inspection Violations

Exit(s) blocked

3.2 Exit(s) blocked.

Violation found on 06/08/2021

Will be rechecked on or after

07/08/2021

Violation Not Repaired

Trip hazards in means of egress.

3.25 Remove tripping hazard(s).

Violation found on 06/08/2021

Will be rechecked on or after

07/08/2021

Violation Not Repaired

Breaker panel(s) not accessible.

4.22 Breaker panel(s) shall be accessible.

Violation found on

Will be rechecked on or after

07/08/2021

Violation Not Repaired

Extension cord(s) cannot replace permanent electrical wiring.

4.4 Extension cord not being used per it's listing.

Violation found on

Will be rechecked on or after

Violation Not

06/08/2021

06/08/2021

07/08/2021

Repaired

Electrical junction boxes are required to be covered.

4.9 Junction box cover(s) required.

Inspector Notes: Second floor dresser room

Violation found on 06/08/2021

Will be rechecked on or after

07/08/2021

Violation Not Repaired

Required ceiling tiles missing.

14.9 Replace missing ceiling tiles.

Violation found on 06/08/2021

Will be rechecked on or after

07/08/2021

Fire alarm system is required to have annual inspection.

5.1 Fire alarm annual inspection required.

Violation found on 06/08/2021

Will be rechecked on or after 07/08/2021

Violation Not Repaired

Provide copy of annual fire alarm system inspection report.

5.2 Fire alarm inspection report required.

Violation found on 06/08/2021

Will be rechecked on or after 07/08/2021

Violation Not Repaired

Fire alarm system is in need of repair.

5.4 Fire alarm system in need of service or repair.

Inspector Notes: Trouble mode

Violation found on 06/08/2021

Will be rechecked on or after

Violation Not Repaired

07/08/2021

Fire sprinkler system is required to have annual inspection.

6.1 Fire sprinkler system annual inspection required.

Violation found on 06/08/2021

Will be rechecked on or after

Violation Not Repaired

07/08/2021

Provide annual inspection report.

6.3 Fire sprinkler inspection report required.

Violation found on 06/08/2021

Will be rechecked on or after

Violation Not

07/08/2021

Repaired

Suppression system is required to be inspected by licensed company every six months.

10.1 Suppression system six month inspection required.

Violation found on 06/08/2021

Will be rechecked on or after

Violation Not

07/08/2021

Repaired

Provide copy of suppression system inspection report.

10.2 Hood fire suppression system inspection report required.

Violation found on 06/08/2021

Will be rechecked on or after

Violation Not

07/08/2021

Repaired

Hood and-or filters need to be properly cleaned.

10.6 Hood system cleaning required.

Violation found on 06/08/2021

Will be rechecked on or after

Violation Not Repaired

07/08/2021

Secure all compressed gas cylinders.

13.12 Secure cylinders.

Violation found on 06/08/2021

Will be rechecked on or after 07/08/2021

Violation Not Repaired

Back flow certification required.

6.39 Back flow certification required.

Violation found on 06/08/2021

Will be rechecked on or after

07/08/2021

Thursday, 17 June, 2021

Attn: Michael Deluca The Big Easy Casino 817 N Federal HWY Hallandale Beach, FL 33009 Property Address: The Big Easy Casino 831 N Federal HWY Hallandale Beach, FL 33009

Re: Initial - Annual Fire Inspection on April 27 2021

An annual fire inspection of your occupancy revealed no violations at the time of this inspection. Thank you for your commitment to maintaining a fire safe occupancy.

Inspector:	Property Representative:	
Fire Safety Inspector Jack-Luis Charles, Jr	Michael Deluca	
Jack-luis_Charles@sheriff.org		
954-405-5768		

The Big Easy Casino **Annual Fire Inspection**

Inspection on April 27 2021 Violations repaired / total: 10 / 10

Violation/Information Page(s)

General Inspection Information

This inspection was performed using the following chapter of the Florida Fire Prevention Code.

CH13 - Existing Assembly (Ch. 13)

Inspection Violations

Electrical junction boxes are required to be covered.

4.9 Junction box cover(s) required.

Violation found on 04/27/2021

Will be rechecked on or after

05/27/2021

Repaired on 06/08/2021

Provide copy of annual fire alarm system inspection report.

5.2 Fire alarm inspection report required.

Violation found on 04/27/2021

Will be rechecked on or after

05/27/2021

Repaired on 06/08/2021

Fire sprinkler system is required to have annual inspection.

6.1 Fire sprinkler system annual inspection required.

Violation found on 04/27/2021

Will be rechecked on or after

05/27/2021

Repaired on 06/08/2021

Replace any missing or broken escutcheon plates.

6.4 Fire sprinkler escutcheon plate(s) required.

Violation found on 04/27/2021

Will be rechecked on or after

05/27/2021

Repaired on 06/08/2021

Copy of fire pump report required.

8.3 Fire pump inspection report required.

Violation found on 04/27/2021

Will be rechecked on or after

05/27/2021

Repaired on 06/08/2021

Replace ceiling tiles around sprinkler heads.

14.9 Replace missing ceiling tiles.

Violation found on

Will be rechecked on or after

05/27/2021 04/27/2021

Repaired on 06/08/2021

Fire extinguishers must be properly mounted.

1.3 Fire extinguisher(s) must be properly mounted. The bottom of the fire extinguisher must be > 4" from the floor and top of fire extinguisher must be < 5' from the floor.

Violation found on

Will be rechecked on or after

Repaired on 06/08/2021

04/27/2021

05/27/2021

Provide a copy of suppression system inspection report.

9.3 Fire suppression system inspection report required.

Violation found on

Will be rechecked on or after

Repaired on

04/27/2021

07/08/2021

06/08/2021

Suppression system is required to be inspected by licensed company every six months.

10.1 Suppression system six month inspection required.

Violation found on

Will be rechecked on or after

Repaired on

04/27/2021

07/08/2021

06/08/2021

Back flow certification required.

8.21 Back flow certification required.

Violation found on 04/27/2021

Will be rechecked on or after

05/27/2021

Repaired on 06/08/2021

Tuesday, 15 June, 2021

954-405-5768

Attn: Greg Jarmon Cheetah Gentlemen's Club 100 Ansin Blvd Hallandale Beach, FL 33009



Property Address: Cheetah Gentlemen's Club 100 Ansin Blvd Hallandale Beach, FL 33009

Re: Initial - Annual Fire Inspection on June 15 2021

An annual fire inspection of your occupancy revealed the violation(s) listed below. Prompt action to correct the following violation(s) is required. The violation(s) must be corrected within the time frame provided.

Per the Florida Fire Prevention Code (7th Edition), NFPA 1:10.2.1 The owner, operator, or occupant shall be responsible for compliance with this Code.

Inspector:	Property Representative:	
Fire Safety Inspector Jack-Luis Charles, Jr	Greg Jarmon	
Jack-luis_Charles@sheriff.org		

Cheetah Gentlemen's Club Annual Fire Inspection

Inspection on June 15 2021 Violations repaired / total: 0 / 5

Violation/Information Page(s)

General Inspection Information

This inspection was performed using the following chapter of the Florida Fire Prevention Code.

CH13 - Existing Assembly (Ch. 13)

Inspection Violations

Fire alarm system is in need of repair.

5.4 Fire alarm system in need of service or repair.

Inspector Notes: The system is on trouble mode.

Violation found on 06/15/2021

Will be rechecked on or after 07/15/2021

Violation Not Repaired

Replace ceiling tiles around sprinkler heads.

14.9 Replace missing ceiling tiles.

Inspector Notes: Couple locations

Violation found on

Will be rechecked on or after

Violation Not Repaired

06/15/2021

07/15/2021

Fire Department Connection sign is not visible and-or not installed properly.

7.10 Fire department connection (FDC) sign missing and/or obscured.

Violation found on 06/15/2021

Will be rechecked on or after

Violation Not

07/15/2021

Repaired

Hood and-or filters need to be properly cleaned.

10.6 Hood system cleaning required.

Violation found on

Will be rechecked on or after

Violation Not

06/15/2021

07/15/2021

Repaired

Building address must be visible.

14.5 Street address required on front of building. (NFPA 1:10.11.1.1)

Violation found on

Will be rechecked on or after

Violation Not

06/15/2021

07/15/2021

Repaired

Monday, 7 June, 2021

Attn: Joe Franco Oceans 11

954-405-5768



Property Address: OCEANS 11 800 N Federal Hwy Hallandale Beach, FL 33009

Re: Initial - Annual Fire Inspection on June 07 2021

An annual fire inspection of your occupancy revealed the violation(s) listed below. Prompt action to correct the following violation(s) is required. The violation(s) must be corrected within the time frame provided.

Per the Florida Fire Prevention Code (7th Edition), NFPA 1:10.2.1 The owner, operator, or occupant shall be responsible for compliance with this Code.

Inspector:	Property Representative:	
Fire Safety Inspector Jack-Luis Charles, Jr	Joe Franco	
Jack-luis_Charles@sheriff.org		

OCEANS 11
Annual Fire Inspection

Inspection on June 07 2021 Violations repaired / total: 0 / 4

Violation/Information Page(s)

General Inspection Information

This inspection was performed using the following chapter of the Florida Fire Prevention Code.

CH13 - Existing Assembly (Ch. 13)

Inspection Violations

Extension cord(s) cannot replace permanent electrical wiring.

4.4 Extension cord not being used per it's listing.

Violation found on 06/07/2021

Will be rechecked on or after 07/07/2021

Violation Not Repaired



Hood and-or filters need to be properly cleaned.

10.6 Hood system cleaning required.

Violation found on 06/07/2021

Will be rechecked on or after

07/07/2021

Violation Not Repaired

K class extinguisher sign required.

1.11 K class fire extinguisher sign required.

Violation found on 06/07/2021

Will be rechecked on or after

07/07/2021

Secure all compressed gas cylinders.


13.12 Secure cylinders.

Violation found on 06/07/2021

Will be rechecked on or after 07/07/2021



Tuesday, 8 June, 2021



Property Address: FLANIGANS 4 N Federal Hwy Hallandale Beach, FL 33009

Re: Initial - Annual Fire Inspection on June 08 2021

An annual fire inspection of your occupancy revealed no violations at the time of this inspection. Thank you for your commitment to maintaining a fire safe occupancy.

Inspector:	Property Representative:	
Fire Safety Inspector Jack-Luis Charles, Jr	Kathy Jones	
Jack-luis_Charles@sheriff.org		
954-405-5768		

FLANIGANS
Annual Fire Inspection

Inspection on June 08 2021 Violations repaired / total: 0 / 0

Violation/Information Page(s)

General Inspection Information

This inspection was performed using the following chapter of the Florida Fire Prevention Code.

CH13 - Existing Assembly (Ch. 13)

Thursday, 17 June, 2021

954-405-5768





Property Address: Club Fate 601 Silks Run 2499 Hallandale Beach, FL 33009

Re: Initial - Annual Fire Inspection on March 15 2021

An annual fire inspection of your occupancy revealed the violation(s) listed below. Prompt action to correct the following violation(s) is required. The violation(s) must be corrected within the time frame provided.

Per the Florida Fire Prevention Code (7th Edition), NFPA 1:10.2.1 The owner, operator, or occupant shall be responsible for compliance with this Code.

Inspector:	Property Representative:	
Fire Safety Inspector Jack-Luis Charles, Jr	Rima Judeh	
Jack-luis_Charles@sheriff.org		

Inspection on March 15 2021 Violations repaired / total: 0 / 4

Violation/Information Page(s)

General Inspection Information

This inspection was performed using the following chapter of the Florida Fire Prevention Code.

CH13 - Existing Assembly (Ch. 13)

Inspection Violations

Emergency light(s) not operating correctly and need to be repaired.

2.6 Emergency light(s) needs service.

Violation found on 03/15/2021

Will be rechecked on or after

04/14/2021

Violation Not Repaired

Sign stating Door to remain unlocked required.

2.15 "THIS DOOR TO REMAIN UNLOCKED WHEN THE BUILDING IS OCCUPIED." sign required.

Violation found on 03/15/2021

Will be rechecked on or after 04/14/2021



Fire rated separation is required.


14.18

Penetration(s) in rated assembly must be properly sealed and/or repaired.

Violation found on 03/15/2021

Will be rechecked on or after 04/14/2021

Violation Not Repaired



Secure all compressed gas cylinders.

13.12 Secure cylinders.

Violation found on 03/15/2021

Will be rechecked on or after 04/14/2021

Tuesday, 8 June, 2021

954-405-5768

Attn: Karla Nunez Chapultepec Mexican Bar & Restaurant 19 NW 2 Ave Hallandale Beach, FL 33009



Property Address: Chapultepec Mexican Bar & Restaurant 23 NW 2 Ave Hallandale Beach, FL 33009

Re: Initial - Annual Fire Inspection on June 08 2021

An annual fire inspection of your occupancy revealed the violation(s) listed below. Prompt action to correct the following violation(s) is required. The violation(s) must be corrected within the time frame provided.

Per the Florida Fire Prevention Code (7th Edition), NFPA 1:10.2.1 The owner, operator, or occupant shall be responsible for compliance with this Code.

Inspector:	Property Representative:	
Fire Safety Inspector Jack-Luis Charles, Jr	Karla Nunez	
Jack-luis_Charles@sheriff.org		

Chapultepec Mexican Bar & Restaurant Annual Fire Inspection

Inspection on June 08 2021 Violations repaired / total: 0 / 1

Violation/Information Page(s)

General Inspection Information

 $This \ inspection \ was \ performed \ using \ the \ following \ chapter \ of \ the \ Florida \ Fire \ Prevention \ Code.$

CH13 - Existing Assembly (Ch. 13)

Inspection Violations

Required ceiling tiles missing.

14.9 Replace missing ceiling tiles.

Violation found on 06/08/2021

Will be rechecked on or after 07/08/2021