EXHIBIT 8

Nightclub Inspections Report FY 2019 / 2020

Location / Address	Trade	Inspector	Date	Hours	Results	Comments
CHAPULTEPEC MEXICAN BAR & REST.	Building	Oscar Brookins	5/28/2019	1	Approved	
23 N.W. 2 ND AVE	Mechanical	Gonzalo Concuero	5/28/2019	1	Approved	
	Electrical	Doug Wansor	6/19/2019	1	Denied	Cabling in kitchen area needs securing. Faceplate needed in dining area
	Plumbing	Robert Stewart	5/28/2019	1		collected grease interceptor and health dept forms
TATIANA	Building	Oscar Brookins	5/28/2019	1	Approved	
1710 E. HALLANDALE BEACH BLVD.	Mechanical	Gonzalo Concuero	5/28/2019	1	Approved	
	Electrical	Doug Wansor	6/12/2019	1	Denied	
			3/12/2010		Demed	Electrical panel clearances. GFI required in kitchen area. Extension cords need removal. Electrical panel need securing in kitchen. Face plate in DJ area needs replacement. Wall sconces damaged in storage area, fire hazard.
	Plumbing	Robert Stewart	5/28/2019	1	Approved	collected grease interceptor and health dept forms
FLANNIGAN'S SEAFOOD BAR AND GRII	Building	Oscar Brookins	5/28/2019		Approved	
4. N. FEDERAL HIGHWAY	Mechanical	Gonzalo Concuero	5/28/2019		Approved	
	Electrical	Doug Wansor	6/12/2019			Openings in boxes in kitchen. Receptacle in dining area needs replacement.
	Plumbing	Robert Stewart	5/28/2019		Approved	collected grease interceptor and health dept forms
GULFSTREAM PARK FOOD & BEVERAG	Building	Oscar Brookins	5/28/2019		Approved	
901 S. FEDERAL HIGHWAY		Gonzalo Concuero	6/18/2019		Approved	
ORCHID CONCESSIONS		Doug Wansor	6/18/2019		Denied	GFI required in kitchen and bar areas. Broken plug prongs in ceiling outlets need
	Plumbing	Robert Stewart	6/18/2019	1	Approved	removal. Exposed wiring needs box installed collected grease interceptor and health dept forms
THE BIG AND EASY CASINO		Oscar Brookins	6/11/2019		Approved	conected grease interceptor and nealth dept forms
831 N. FEDERAL HIGHWAY		Gonzalo Concuero	6/11/2019		Approved	
		Doug Wansor	6/25/2019		Approved	
		Robert Stewart	6/11/2019		Approved	
		Oscar Brookins	5/28/2019			
800 N. FEDERAL HIGHWAY		Gonzalo Concuero	5/28/2019		Approved	
		Doug Wansor	6/26/2019		Approved	
		Robert Stewart	5/28/2019		Approved	
						collected grease interceptor and health dept forms
NO. E		Oscar Brookins	5/28/2019		Approved	
		Gonzalo Concuero	5/28/2019		Approved	
		Doug Wansor	6/18/2019		Denied	GFI required in kitchen areas and exterior. Boxes need resecuring in parking lot.
	Plumbing	Robert Stewart	5/28/2019	1].	Approved	collected grease interceptor and health dept forms
ATE	Ruilding T	Occar Breaking	0/44/0046			
601 SILKS RUN Suite 2499		Oscar Brookins	6/11/2019		Approved	
		Gonzalo Concuero	6/20/2019		Approved	
		Doug Wansor	6/19/2019		Denied	Faceplates missing for receptacles in club area. GFI required resecuring in parking lo
		Robert Stewart	6/20/2019		Approved	collected grease interceptor and health dept forms
		Oscar Brookins	5/28/2019	1	Approved	
E		Gonzalo Concuero	6/19/2019	1 ,	Approved	
		Doug Wansor	6/12/2019	1 ,	Approved	
	Plumbing	Robert Stewart	6/19/2019	1	Approved	collected grease interceptor and health dept forms

Total Hours